









Date: Wednesday, 6/27/2007 2:46:36 PM
User: Jason Murdoch

Process Sheet

Customer : CC-DAR01 Dart Aerospace Ltd.	Drawing Name : D3368-041
Job Number : 33238	
Estimate Number : 10804	
P.O. Number : NIA	Part Number : D3368041
This Issue : 6/27/2007 S.O. No. : NIA	Drawing Number : R611
Prsht Rev. : NC	Project Number : NIA
First Issue : NIA Type : SMALL /MED FAB	Drawing Revision : NIA
Previous Run : 00015	Material : NIA
Written By : _____	Due Date : 7/4/2007 Qty: 1 Um: Each
Checked & Approved By : _____	
Comment : _____	

Additional Product

Job Number: 

Seq. #:	Machine Or Operation:	Description :
1.0	QC5	INSPECT WORK TO CURRENT STEP
  <p>Comment: INSPECT WORK TO CURRENT STEP</p> <p><i>07-06-27 (1)</i></p>		
2.0	D3368041	Pedal Lock Assembly
  <p>Comment: Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)</p> <p>Pedal Lock Assembly</p> <p>Original Batch B30977. R611</p> <p><i>07/06/28 @</i></p>		
3.0	PACKAGING 1	PACKAGING RESOURCE #1
  <p>Comment: PACKAGING RESOURCE #1</p> <p>New labels required</p> <p>re-identify paperwork</p> <p>re-package and stock</p> <p><i>07/06/28 @</i></p>		
4.0	QC21	FINAL INSPECTION/W/O RELEASE
  <p>Comment: FINAL INSPECTION/W/O RELEASE</p> <p><i>07.07.18</i></p> <p><i>HA</i></p>		

Job Completion 

U 07.07.18